# **Technical Bulletin**



TB- 101952 / November 2017

## Lowrance display software update

Product:
Product Description:
Software Version:
Effective Date:
Inspect/Update Current Inventory:

Carbon, HDS Gen3, Elite-Ti Carbon 16, 12, 9, 7: HDS Gen3 12, 9, 7: Elite Ti 12, 9, 7, 5 See table below 16<sup>th</sup> November 2017 Yes

Model	Version	File name
Carbon	3.0	HDS_Carbon-3.0-58.1.94-Standard-1.upd
HDS Gen3	6.0	HDS_Gen3-6.0-58.1.94-Standard-1.upd
Elite Ti	4.0	EliteTi-4.0-58.1.94-Standard-1.upd

### **New Feature for GEN3 & CARBON**

#### Yamaha engine integration



Yamaha<sup>®</sup> Command Link / Command link Pro engine information can now be displayed on Lowrance Gen3 and Carbon head units. (This feature is not available for Elite-Ti).

When a Carbon or GEN3 and compatible Yamaha gateway are connected to the same NMEA 2000 network, the Yamaha features are unlocked on the display. A Yamaha engine icon is available on the HOME screen. The Yamaha on-screen interface is the very similar to that of the Yamaha CL7 Gauge.

In this version of software, a compatible gateway is either a Yamaha CL7 Gauge or a combination of Gateway (6YG-8A2D0-00-00) <u>AND</u> a Yamaha 6Y9 Gauge. For more information, please refer to the Yamaha Integration guide on the Lowrance website.

The Yamaha interface feature can support and display information of up to four engines. Four engines can be displayed either on one MFD or spread across two displays (Port + Port CENTER on one MFD and STBD CENTER and STBD on another MFD)





## Improvements for Gen 3, Carbon and Elite-Ti

#### Performance increases and optimizations

Lowrance displays should appear to run smoother and faster with this software compared to earlier 56 and 57 versions. Chart redraw speeds and speed moving from page to page has been improved.

Note: We have one outstanding issue related to Navionics Sonar Chart Live feature. Extended logging can gradually make the chart feature appear slow to respond and redraw. We are working hard with the chart vendor to resolve this.

#### **Fixes**

- Reports of displays with built in WiFi having Intermittent connection to WiFi hot spots has been resolved
- Tide station search not working when set to Language other than English

For more information: lowrance.emea@navico.com

